CERTIFICATE OF DEDICATION AND OWNERSHIP

Know all men by these presents that Union Pacific Railroad Company, being sole owner in fee simple of all that real property situated in the Town of Minturn, Eagle county, Colorado described as follows: A Parcel of land being a portion of the Northwest Quarter, of Section 26, Township 5 South, Range 81 West of the

Sixth P.M. according to the Dependent Resurvey thereof accepted September 13, 1943 and also being a portion of the lands defined in the Quitclaim Deed recorded December 2, 2014 as Reception No. 201420764 and being more particularly described as follows:

Beginning at a point on the North Line of said Section 26 from which the Northwest Corner of said Section bears N89°57'12"W 617.57 feet; thence upon said North Section line S89°57'12"E 676.63 feet, to the northwest corner of lands plated as, Palmateer Parcels recorded as Reception No. 200824176; thence departing said North Section line and upon the western boundary of said Palmateer Parcels and upon the western line of lands platted with document recorded as Reception No. 225471 the following three (3) courses 1) S00°54'37"E 582.09 feet; 2) N89°17'04"E 19.82 feet; 3) S00°38'41"E 11.65 feet to the western boundary of Taylor Avenue Dedication recorded as Reception No. 144697; thence upon said western boundary of Taylor Avenue the following nineteen (20) courses: 1) S61°43'33"W 0.57' 2) 146.86 feet upon a curve to the left having a radius of 123.25 feet the chord of which bears S27°35'25"W 138.33 with a central angle of 68°16'25"; 3) S06°32'44"E 191.80 feet; 4) 97.75 feet upon a curve to the right having a radius of 294.17 feet the chord of which bears S02°58'26"W 97.31 with a central angle of 19°02'23" to a point of reverse curve; 5) 136.62 feet upon a curve to the left having a radius of 315.79 feet the chord of which bears S00°06'00"W 135.56 with a central angle of 24°47'18"; 6) S12°17'38"E 36.23 feet; 7) 36.82 feet upon a curve to the right having a radius of 237.18 feet the chord of which bears S07°50'50"E 36.78 with a central angle of 08°53'38"; 8) S03°24'01"E 331.37 feet; 9) 56.70 feet upon a curve to the right having a radius of 354.36 feet the chord of which bears S01°04'30"W 56.64 feet with a central angle of 09°10'04"; 10) S05°39'15"W 31.82; 11) 61.97 feet upon a curve to the left having a radius of 613.32 feet the chord of which bears S02°45'35"W 61.94 feet with a central angle of 05°47'20"; 12) S00°08'06"E 130.70 feet; 13) 51.69 feet upon a curve to the left having a radius of 600.87 feet the chord of which bears S02°35'58"E 51.67 feet with a central angle of 04°55'43"; 14) S05°03'50"E 70.50 feet; 15) 38.39 feet upon a curve to the right having a radius of 483.44 feet the chord of which bears S02°47'20"E 38.38 feet with a central angle of 04°33'00"; 16) S00°30'50"E 233.54 feet; 17) 39.30 feet upon a curve to the right having a radius of 1128.82 feet the chord of which bears S00°29'01"W 39.30 feet with a central angle of 01°59'41"; 18) S01°28'51"W 104.95 feet; 19) 152.32 feet upon a curve to the right having a radius of 247.77 feet the chord of which bears S19°05'31"E 149.93 feet with a central angle of 35°13'22"; 20) S36°42'11"W 48.35 feet; thence departing said Taylor Avenue, the following eleven (11) courses: (1) 211.61 feet upon a curve to the left having a radius of 2208.58 feet the chord of which bears N05°16'34"W 211.53 feet with a central angle of 05°29'23"; (2) N08°01'15"W 215.43 feet; (3) 252.18 feet upon a curve to the left having a radius of 2013.41 feet the chord of which bears N11°36'33"W 252.02 feet with a central angle of 07°10'35"; (4) N15°11'50"W 538.46 feet; (5) N14°53'24"W 239.29 feet; (6) 127.07 feet upon a curve to the right having a radius of 800.55 feet the chord of which bears N11°48'34"W 126.94 feet with a central angle of 09°05'41"; (7) N07°15'43"W 164.66 feet; (8) 143.34 feet upon a curve to the left having a radius of 763.58 feet the chord of which bears N12°38'24"W 143.13 feet with a central angle of 10°45'20"; (9) N18°01'03"W 324.55 feet; (10) 60.43 feet upon a curve to the left having a radius of 2813.69 feet the chord of which bears N18°37'58"W 60.43 feet with a central angle of 01°13'50";(11) N19°14'54"W 346.49 feet to the Point of Beginning. Containing 18.955 acres more or less; and has caused the same to be laid out, platted and subdivided, and designated as UPRR SUBDIVISION, a Subdivision in the Town of Minturn, County of Eagle, Colorado, and does hereby accept responsibility for the completion of the improvements required by this plat, and do hereby dedicate and set aside all of the roads and other public improvements and places as shown on the accompanying plat to the use of the public

OWNER: Union Pacific Railroad Company ADDRESS: 1400 Douglas Street, MS 1640, Omaha, NE 68179

Chris D. Goble TITLE: Assistant Vice President - Real Estate STATE OF NEBRASKA)

COUNTY OF DOUGLAS)

THE FOREGOING CERTIFICATE OF DEDICATION AND OWNERSHIP WAS ACKNOWLEDGED BEFORE _, A.D, 20___, BY CHRIS D. GOBLE AS ASSISTANT VICE PRESIDENT- REAL ESTATE OF UNION PACIFIC RAILROAD COMPANY.

MY COMMISSION EXPIRES: _____ WITNESS MY HAND AND OFFICIAL SEAL

NOTARY PUBLIC

MINTURN TOWN CERTIFICATE

This plat is approved by the Town Council of the Town of Minturn, County of Eagle, State of Colorado this ____ day of _____, 2023, for filing with the Clerk and Recorder of the County of Eagle, Colorado, and for conveyance of the dedications shown hereon; subject to the provisions that approval in no way obligates the Town of Minturn for financing or construction of improvements of said lands, streets or easements dedicated to the public, except as specifically agreed to by the Town Council of the Town of Minturn.

WITNESS MY HAND AND THE SEAL OF THE TOWN OF MINTURN TOWN COUNCIL OF THE TOWN OF MINTURN

ATTEST:

MAYOR


TOWN OF MINTURN, COLORADO

TOWN CLERK

TOWN OF MINTURN, COLORADO

FINAL PLAT UPRR SUBDIVISION

Town of Minturn, County of Eagle, State of Colorado



PORTION OF SECTION 26, TOWNSHIP 5 SOUTH, RANGE 81 WEST, 6th P.M.

SURVEYOR'S CERTIFICATE

I, Matthew S. Slagle, do hereby certify that I am a Professional Land Surveyor licensed to practice land surveying under the laws of the State of Colorado, That this Subdivision Plat is a true, correct and complete plat of UPRR SUBDIVISION, as laid out, platted, dedicated and shown hereon. that such plat was made from an accurate survey of said property by me and /or under my supervision and accurately shows the location and dimensions of the lots, easements and rights-of-way of said plat as the same are monumented upon the ground in compliance with applicable regulation governing the subdivision of land, that such plat is based upon the professional land surveyor's knowledge, information and belief, that it has been prepared in accordance with applicable standards of practice, and that such plat is not a guaranty or warranty, either expressed or implied.



Matthew S. Slagle PLS 34998 Professional Land Surveyor State of Colorado

LAND USE TABLE

PARCEL	USE	AREA	ADDRESS
1	Residential	13.485 Acres	0100 Minturn Road
2	Residential	5.470 Acres	0500 Minturn Road
TOTAL		18.955 ACRES	

ADDRESSES ARE FOR INFORMATIONAL PURPOSES ONLY

		t the entire amount of taxes and as Il parcels of real estate described o	ssessments due and payable as ofon this Plat are paid in full.
		, A.D., 20	-
		TREASURER OF EAGLI	E COUNTY
	does hereb is vested in ens, taxes, and enc		itle to all lands shown upon this plat
DATED THIS	DAY OF		
		AGENT:	
by Eagle Valley Surv 3) Survey Date: June 4) Legal description, Insurance Company of 02, 2014 as Reception to items referenced in were not researched be issues. Item 9 - Pipe easem Sec 26, T5S, R81W. Item 11&12- Ordinated in Book 248 Item 13 - 20 foot Secure 14 - Conveyant Item 15 - Does not of Minturn. Item 16 - effects sull Page 349. Item 17 & 18- Doen Item 19 - Conveyant hereon. Item 20 - Does not Item 22 - Public Secure 14 - Conveyant hereon. Item 25 & 26 - Parcel document recorded as thereof not clear to sull Item 29 - Parcel is secure 29 - Parcel is secure 29 - Parcel is secure 236938, ii) Aduit 2720	ey and dated August & July 2023. easements and locorder number ABC in No. 201420764 and schedule B II of the sy surveyor or found and a schedule B II of the sy surveyor or found and a schedule B II of the sy surveyor or found and a property and a schedule B II of the sy surveyor or found and a property and a schedule B II of the sy surveyor or found and a schedule B II of the seement, Donce to State Departs effect these Platted bject parcel as it is not effect subject parcel as it is not effect these Platted as Reception No. 20 arveyor from face of the subject to Manual Schedule B II of the second as Reception No. 20 arveyor from face of subject to 1904 40 section of which is not to the Recording ds are subject to Union 19056, iii) Audit No. No. 272056, viii) A	eation of boundary lines are based of 50050645-9, dated August 03, 202 long with plats and survey monuments title commitment referenced about to not contain easement restrictions. This platted parcel, falls in Norther Book 248 at Page 452. Does not effect this platted Parcel. The ment of Highways, Does not Effect lands but references vacation of plant an Annexation of property to Townstarcel. Dook 687 at Page 268 does not contain days. (a.k.a. subject parcel) Colorado Easement, Reception Noted as Reception Noted Reception Noted As Reception Noted Reception N	23, Quitclaim Deed recorded Decembration referenced hereon. In regard love: Items 1-8, 10, 21, 24, 27 and 30 cons or other survey or platting related ast Quarter of the Northwest Quarter acted hereon by eastern Boundary, but these platted lands. Portions of Taylor Addition to the Town of Minturn recorded in Book 333 and any easements not already defined as a djoiner hereon. The subject parcel defined in the subject parcel
	record in the Offic	ce of the Clerk and Recorder at, A.D, 20	o'clock, on this
CLERK AND RECOR	RDER	DEPUTY	Revised Boundary Dim 11-07-23 Revised in House 10-06-23 M Revised Legal Call 09-27-23 M Revised Per In House 08-22-23 M Revised Per In House 08-18-23 M Revised Boundary 07-24-23 MS



SLAGLE SURVEY SERVICES

800 Castle Drive - P.O. Box 751 Eagle, Colorado 81631 970.471.1499 Office matthew@slaglesurvey.com www.SlagleSurvey.com

FINAL PLAT **UPRR SUBDIVISION**

Town of Minturn, County of Eagle, State of Colorado

DRAWING NAME: 22055 UPRR FP.dwg 22055 MSS $_{\mathsf{OF}} \quad 1 \quad _{\mathsf{OF}} \quad 2$ 06-03-2023

NOTICE: ACCORDING TO COLORADO LAW YOU MUST COMMENCE ANY LEGAL ACTION BASED UPON ANY DEFECT IN THIS SURVEY WITHIN THREE YEARS AFTER YOU FIRST DISCOVERED SUCH DEFECT. IN NO EVENT, MAY ANY ACTION BASED UPON ANY DEFECT IN THIS SURVEY BE COMMENCED MORE THAN TEN YEARS FROM THE DATE OF CERTIFICATION SHOWN HEREON.

FINAL PLAT UPRR SUBDIVISION Town of Minturn, County of Eagle, State of Colorado SHEET 2 OF 2 FOUND SURVEY MONUMENT 1.25" RED PLASTIC CAP ON REBAR STAMPED LS 26626 FOUND SURVEY MONUMENT FOUND SURVEY MONUMENT 1.5" ALUMINUM CAP ON REBAR C-W 1/16 SEC 26 3.25" DIAMETER USFS 410 392 362 **35**2 R=1128.82 FOUND SURVEY MONUMENT R=247.77 ALUMINUM CAP ON 2" TUBE STAMPED LS 7235 1981 292 452 R=613.32 372 442 434 & 436 W 1/16TH SEC 26 / 23 L=39.30L=152.32498 R=294.17 RECEPTION L=61.97472 T=19.65T=78.652.5" BRASS D.O.A. CAP IN STONE No. 225471 FOUND SURVEY MONUMENT L=97.75 |531 T=31.01CD=S00°29'01"W CD=S19°05'31"W STAMPED LS 7235 RAIL MONUMENT LOCATION MINTURN T = 49.33CD=S02°45'35"W TAYLOR AVENUE CH = 39.30CH=149.93 N87*49'11"W 85.40' FROM C-W SET SURVEY MONUMENT TOWNE HOMES CD=S02°58'26"W 40' PUBLIC RIGHT-OF-WAY PARCEL C CH=61.94 S00°38'41"E % 2" ALUMINUM CAP ON No. 5 REBAR STAMPED LS, 34998 1/16 TH - 2.5" ALUMINUM CAP ON No.6 REBAR STAMPED PLS D=1°59'41" D=3513'22" PALMATEER PARCELS CH = 97.31RN 144697 RECEPTION No. 200824176 D=19'02'23" & RECEPTION NO. 200824177 S01°28'51"W 104.95 S00°30'50"E 233.54 582.09 S03°24'01"E 331.37 S00°54'37"E ASPHALT S12.17'38"E R=600.87 70.50 FOUND SURVEY MONUMENT L=38.39 T=19.21 UTILITY UPRR L=56.701.5" ALUMINUM CAP ON REBAR L=51.69(S00°55'00"E 469.08) AUDIT T = 28.41STAMPED LS 5447 R=237.18 T=25.86FOUND SURVEY MONUMENT R=315.79 No., 236938 CD=S02°47'20"E CD=S01°04'30"W L=36.82 T=18.45 DISTURBED NO. 5 REBAR CD=S02°35'58"E L=136.62 P CH=38.38 FIRE HYD L=146.86 USED SPUN LOCATION & CH = 56.64CH = 51.67T=69.40T=83.56D=4.33,00, & VALVE IRMED UP REBAR- NOT ACCEPTED D=9°10'04" CD=S07'50'\$0" 2" ALUMINUM CAP ON NO. 5 D=4°55'43" CD=S00°06'00"W CD=S27°35'25"W REBAR STAMPED LS 34998 S50°23'W 0.90' TO REBAR PARCEL 1 CH=36.78 \CH=135.56 FOUND SURVEY MONUMENT CH=138.33 (FOUND DISTURBED No. 5 REBAR) D=8°53'38'\ $D=24^{4}7'18''$ 13.485 Acres 1.5" ALUMINUM CAP ON No. 4 1.5" ALUMINUM CAP ON NO. 5 REBAR STAMPED LS 30116 **(**100) R=2013.41 REBAR STAMPED LS 20695 L=211.61 L=252.18 T=105.89 APPARENT UTILITY T=126.26 CD=N05°16'34"W **\EASEMENT** CD=N11°36'33"W APPARENT UTILITY CH = 211.53CH = 252.02FOUND SURVEY MONUMENT EASEMENT -D=5°29'23" 1" BRAS DISC WITH NAIL D=7°10'35" R=800.55 L=127.07 PARCEL 2 T = 63.675.470 Acres CD=N11°48'34"W R=763.58 CH=126.94 L=143.34D=9°05'41" T=71.88FOUND SURVEY MONUMENT CD=N12°38'24"W 1.5" ALUMINUM CAP ON REBAR STAMPED LS 24318 CH=143.13 D=10°45'20" L=60.43 T=30.22 CD=N18*37'58"W CH=60.43 D=1°13'50" UNION PACIFIC RAILROAD FOUND SURVEY MONUMENT of 1.5" ALUMINUM CAP ON REBAR STAMPED LS 24318 **RECEPTION** No. 201420764 > BEGINNING FOUND SURVEY MONUMENT 5" ALUMINUM CAP ON NO. 5 REBAR STAMPED LS 20695 □ = FOUND 1.5" ALUMINUM CAP ON NO. 5 REBAR STAMPED LS 11204 • FOUND 1.5" ALUMINUM CAP ON NO. 5 REBAR STAMPED LS 20695 ● = FOUND 1.5" ALUMINUM CAP ON NO. 4 REBAR STAMPED LS 30116 S = FOUND 1" BRASS DISC WITH NAIL STAMPED LS 30116 ● = SET 2" ALUMINUM CAP ON NO. 5 REBAR STAMPED LS 34998 P = PHONE OR COMMUNICATION PEDESTAL = MARKER FOR BURIED GAS UTILITY θ = UTILITY POLE ₩ = WATER VALVE Matthew S. Slagle PLS 34998 FOUND SURVEY MONUMENT Professional Land Surveyor W 1/4 SEC 26 2.5" DIAMETER USGLO BRASS CAP STAMPED 1942 State of Colorado 1 INCH = 100 FEET2788.54 S00°41'20"E WEST LINE SECTION 26 T5S R81W FOUND SURVEY MONUMENT NW CORNER SEC 26 T5S R81W 6TH PM 2.5" USGLO BRASS CAP ON 1" PIPE - STAMPED 1942 NOTICE: According to Colorado law you must commence any legal (LOCATED BASE OF LEANING PIPE) action based upon any defect in this survey within three years after you first discovered such defect. In no event, may any action based upon any defect in this survey be commenced more than ten years from the date of certification shown hereon.